

Rickly House Stable

Herrick Archives Number H 103

A. IDENTIFICATION & LOCATION

1. Name

1.1 Building was never officially named by Board of Trustees.

1.2 Alternate names noted:

Rickly House Barn

Barn in rear of Boiler House

Equipment Barn, rear of Boiler House

Horse Barn, Rickly House

Storage Barn, rear of Boiler House

President's House Stable


2. Location

2.1 Originally located northeast of Building 001. See map A below. Later moved to point north of Building 017. See map B below.


For indexing purposes, the following addresses have been arbitrarily assigned:

Original location — 1893 North High Street

Second location - 225 West Eighteenth Avenue



For Identification of other buildings shown, see Appendix A.



For identification of other buildings shown, see Appendix A.

3. General Description

3.1 Type of construction:

Frame, with pine siding and wood shingle roof. Set on stone piers (McC 1:8A).

3.2 No. of stories:

Probably two stories. See 3.4.1 below. Photograph X 2229 suggests that the upper floor was only a loft, and not a full story.

3.3 Increments of construction:

No additions noted.

3.4 Size of building:

3.4.1 Floor space, 1080 sq.ft. (McC 1:8A). Various maps show a building outline about 17 or

18 ft. wide by approximately 30 ft. long. A two story building 18' x 30' would have a floor area of 1080 sq.ft.

3.4.2 Volume, 10,800 cu.ft. (McC 1:8A).

B. CONSTRUCTION, RELOCATION, & DEMOLITION

1. The building was constructed in 1871, according to an Executive Committee report to the Board of Trustees on January 3, 1872.
2. The Board of Trustees on April 9, 1896 authorized the moving of the building.
3. Destroyed by fire in February, 1904 (McC 2:286). In Volume 4 at page 14A, McCracken gives the date of the fire as August, 1904. This discrepancy has not been resolved.

C. COST

\$500 (McC 1:8A)

D. PHOTOGRAPHS

1. In Photoarchives:

X 2229 — building at left margin

John H. Herrick
March 2, 1979

ADDENDUM NO. 1

Inspection of old campus maps reveals the following additional name for this building:

Stable

John H. Herrick
November 10, 1979

ADDENDUM NO. 2

Evidence from old maps contradicts McCracken's reports that this building burned in 1904. It appears on the following maps:

Map 190-09 — 1906 (revised to 1909)
Map 190-13 — October 29, 1906
Map 190-14 — October 1907
Map 190-15 — 1907
Map 190-20 - 1908
Map 190-21 — 1908
Map 190-22 - 1908
Map 190-24 — August 6, 1909
Map 191-01 — January 1910
Map 191-02 — 1910
Map 191-04 — 1910

I have found no report of the fire in the Lantern.

John H. Herrick
December 9, 1980